VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai –2025	DATE	May 30, 2014
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG		
	(Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Loosened piston rod screw connection causes engine crank		
	case breakage. As the result, there is a possibility to catch a		
	fire on the affected vehicles.		

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ABA-991MA175	911 GT3	2014	44
		TOTAL	44