

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3373	DATE	Jun.26 2014
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>There are lack of strength of rubber hose inside of retarder cooling system in the engine cooling system, which accrue to damage rubber hose. If you keep using rubber hose, it will leak coolant water. In the worst case, it may cause of disable an engine and drive.</p> <p>① Rubber hose of retarder side and engine side replace countermeasure parts</p> <p>② Rubber hose of engine side replace countermeasure parts</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
UDS-KRC012	KR-75H	2013~2014	63	①
			69	②
			TOTAL	132