

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2055	DATE	June 25 <sup>th</sup> , 2014
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The bolts on the VANOS (variable valve timing system adjustment unit) on both intake and exhaust camshaft are not robust enough and can be broken. Thus, the system may not operate properly, which causes engine malfunction with engine warning lamp on. In the worst case, engine may turn off while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-UD30	BMW 130i	2009 - 2010	54
ABA-VS25	BMW 325i Touring	2009 - 2010	3
DBA-FP25	BMW 523i	2010	358
DBA-MT25	BMW 523i Touring	2010	122
ABA-NU25	BMW 525i	2009	5
ABA-PU25	BMW 525i Touring	2010	20
DBA-FR30	BMW 528i	2010	1,323
DBA-MU30	BMW 528i Touring	2010	62
ABA-NU30	BMW 530i	2009	2
ABA-PU30	BMW 530i Touring	2009 – 2010	3
ABA-VL25	BMW X1 xDrive 25i	2010	348
ABA-PC25	BMW X3 2.5si	2010	85
CBA-WX30	BMW X3 xDrive 28i	2010 – 2011	227
ABA-PC30	BMW X3 3.0si	2010	1
ABA-FE30	BMW X5 3.0si	2009	2
ABA-LM25	BMW Z4 sDrive 23i	2009 – 2010	254
ABA-UC30	BMW 135i Coupe	2010 – 2011	405
ABA-PM35	BMW 335i	2010 – 2011	313
ABA-UV35	BMW 335i Touring	2010 – 2011	133
ABA-KG35	BMW 335i Coupe	2010 – 2011	254
ABA-DX35	BMW 335i Cabriolet	2010 – 2011	202
CBA-FR35	BMW 535i	2009 – 2011	1,471
DBA-MU35	BMW 535i Touring	2010 – 2011	191
CBA-SN30	BMW 535i GranTourismo	2009 – 2010	574
DBA-SN30		2010 – 2011	74
DBA-LW30C	BMW 640i Coupe	2011	120
DBA-LW30	BMW 640i Cabriolet	2010 – 2011	129

DBA-WX35	BMW X3 xDrive 35i	2010 – 2011	372
ABA-ZV30	BMW X5 xDrive 35i	2010	98
ABA-ZV30S		2010	434
DBA-ZV30		2010 – 2011	128
DBA-ZV30S		2010 – 2011	512
ABA-FG35	BMW X6 xDrive 35i	2010	168
DBA-FG35		2010 – 2011	169
		TOTAL	8,616