

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2037	DATE	June 5, 2014
MANUFACTURE	Caterpillar Japan LTD		
DESCRIPTION OF DEFECT	Electrical harnesses of transmission control lever and others can secured improperly in steering column cover and can cause short circuit. This failure can cause electrical error and/or can disturb machine travel direction change operation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-FER	950K	2013-2014	32
UDS-FLL	962K	2013	2
		TOTAL	34