

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3406	DATE	Jul 31, 2014
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	The hook to hold the spare tire carrier can detach due to peeling at its welding point with improper welding. That can make the spare tire carrier tilted. In the worst case the spare tire might drop and that could disturb traffics in the dropping area.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
EBD-DA16T	CARRY	From 2013 to 2014	13,320
EBD-DR16T	NT100 CLIPPER	From 2013 to 2014	1,440
EBD-DG16T	SCRUM	From 2013 to 2014	695
EBD-DS16T	MINICAB	2014	535
		TOTAL	15,990

The part applied to an unknown vehicle because it was shipped as one of service parts

Part Name	Part No.	Shipment Period of the part	Quantity
Tail Cross Member	59780-82M01	2014	1
		TOTAL	1