VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

	CAMPAIGN No.	3404	DATE	Jul.31 2014		
M	UNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation				
	DESCRIPTION OF DEFECT	On some heavy-duty trucks, the welding of the transmission output shaft is improper. If the vehicle continues to be used in this condition, the welded part of the shaft may break. In the worst case, the vehicle will become unable to drive.				

TYPE	COMMERCIAL NAME		DEL YEAR CALLED	NUMBER OF VEHICLE
PJ-FP54JGR	- 「FUSO SUPER GREAT」	2007~2007		1
BKG-FP54JDR		2007~2009		20
BKG-FP54JER		2007~2008		11
BKG-FP54JGR		2007~2007		1
		TOTAL	33	