

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3390	DATE	July , 22 , 2014
MANUFACTURER	SOHSHIN CO., LTD.		
DESCRIPTION OF DEFECT	Because the shape of a support bracket fixing a fuel tank and a tank is inappropriate, in a fuel tank, a crack may occur by the vibration of the body in the lower part of the fuel tank. Therefore a crack progresses when I continue just using it, and fuel might leak from the crack department concerned when I am the worst.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PY5KUFGM	—	2000~2010	23
PY5KUGM	—	2010~2014	9
		TOTAL	32