

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3388	DATE	Jul. 17, 2014
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	For vehicle equipped with DIT (Direct Injection Turbo) Engine, due to improper ECU (Engine Control Unit) programming, preignition occurs while load of the engine is increased, which may cause spark plug or/and piston to damage. As a result, warning lamp illumination or/and vehicle body vibration occur and, in the worst case, engine may stall.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BRG	「LEGACY」	2012~2014	7,708
DBA-BMG		2012~2014	2,435
		TOTAL	10,143