

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3385	DATE	Jul.9.2014
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	In the spot welding process of the cab on certain light duty trucks, due to improper program of the automatic spot welding machine used for welding of the underbody, there is a possibility that specific spot welds around the seat belt fitting portion could be missing. In this condition, the seat belt fitting portion may be deformed during a crash, causing the seatbelt to not restrain the occupant.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-XZU685M	[Hino Dutro]	2014	1
TKG-XZC605V	[Toyota Dyna200]	2014	2
TKG-XZU605	[Toyota Dyna200] [Toyota ToyoaceG25]	2014	2
TKG-XZU695	[Toyota Dyna200]	2014	1
		TOTAL	6