

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2068	DATE	Jul.9.2014
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the airbag control module, some module could have insufficient proof strength against electrical noise. In this condition, the IC chip in the module could become damaged due to electrical noise generated during operation of the power seat. In the worst case, the airbag(s) could deploy while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TA-MCX20	[PRONARD]	2002-2003	540
		TOTAL	540