VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	3377	DATE	July 8 , 2014		
MANUFACTURER	MITSUBISHI NICHIYU FORKLIFT CO.,LTD.				
DESCRIPTION OF	On battery plug of electrical forklift truck, due to poor crimping, plug				
DEFECT	terminals will become overheated.				
	Therefore, when the truck keeps going under high load, the resin portion				
	of the plug will be deformed by overheat, and thereby might irregularly				
	open the electrical contact between the battery and the truck.				
	The truck would be unable to drive in the worst case.				

TYPE	COMMERCIAL NAME	MOI YE RECA	AR	NUMBER OF VEHICLES
NICHIYU 244AA	T R A N S E R	2 0 0 4		1
		2 0	1 2	1
NICHIYU 254AA		2 0	0 5	1
		2 0	1 2	2
			TOTAL	5