## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3383	DATE	3-July -2014		
MANUFACTURER	KYODO Co. Ltd				
DESCRIPTION OF DEFECT	Electric device (Ignition Coil)				
	In the heavy-duty truck which changed the fuel system into CNG from light oil, since the				
	durability of the ignition coil of an igniter is insufficient, it becomes impossible to carry out				
	sufficient ignition for an early stage, and there is a possibility that backfire and an after fire may				
	occur.				
	Therefore, when use is continued as it is, a throttle valve changes by backfire and, in the worst				
	case, there is a possibility of resulting impossible [ a run ].				

	COMMERCIAL	MODEL		NUMBER OF	
TYPE	NAME	YEA	\R	VEHICLE	
		RECAL	LED		
LKG-CYJ77A kai	「GIGA」	CYJ77A-7000229 ~	CYJ77A-7002731	13	
		2011 ~	2012		
LKG-CYM77AM kai	「GIGA」	CYM77AM-	M-7000085		
		2012	2	<b>'</b>	
LKG-CYL77A kai	「GIGA」	CYL77A-7001371 2012		1	
				'	
QKG-CYJ77A kai	「GIGA」	CYJ77A-7004652 ~ CYJ77A-7005265		7	
		2012 ~ 2013			
QKG-CYL77A kai	「GIGA」	CYL77A-7002831 ~ CYL77A-7002874		1	
		2012 ~ 2013			
			TOTAL	23	