

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3382	DATE	Jul. 3, 2014
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	<p>Due to improper compaction process and/or improper moisture absorption prevention measure for propellant wafers, the density of propellant wafers could be low. These propellant wafers may have been assembled in the passenger air bag inflators. In the event of an air bag deployment with such propellant wafers, pressure within the inflator body may abnormally increase. As a result, the inflator body could rupture, possibly scattering, potentially increasing the risk of fire or injury to the occupant.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TA-BP5 UA-BP5	「LEGACY」	2003	472
TA-BL5		2003~2004	67
		TOTAL	539