

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 3 8 7	DATE	July.1.2014
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>On the A/T of certain ambulance vehicles, the oil pump bush might be partially melted by the excessive heating of the torque converter due to the inappropriate inspection method at the vehicle shipment. If the vehicle continues to be driven in this condition, the damage of the oil pump bush can progress and the sealing performance will deteriorate. This may cause an oil leak, and, in an extreme case, the vehicle cannot be driven.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBF-FPWGE50	「PARAMEDIC」	2013~2014	47
		TOTAL	47