

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3386	DATE	Jul.9.2014
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the spot welding process of the cab on certain light duty trucks, due to improper program of the automatic spot welding machine used for welding of the underbody, there is a possibility that specific spot welds around the seat belt fitting portion could be missing. In this condition, the seat belt fitting portion may be deformed during a crash, causing the seatbelt to not restrain the occupant.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDF-KDY221	[DYNA] [TOYOACE]	2014	1
LDF-KDY231 QDF-KDY231		2014	8
LDF-KDY281		2014	15
ABF-TRY230		2014	9
		TOTAL	33