

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	3 4 1 2	DATE	August 1, 2014
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	<p>Because of improper instructions, tension arm of some machine, that is part of belt drive system of radiator fan, was installed on opposite direction. Consequently, if operators continue to use machine with above condition, the fan belt will be damaged or be come off the tension pulley. In the worst case, it leads to overheat of engine.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDP-H161	「HJ5098」	2014	47
	「HJ6098」	2014	36
		TOTAL	83