VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	3397	DATE	05-Aug-14
MANUFACTURER	YANMAR CONSTRUCTION EQUIPMENT CO. ,LTD.		
DESCRIPTION OF DEFECT	property is not suffi flasher lamp wiring a leak into the joint of Consequently, the of to transmit electric	icient for the connect and horn wiring. This f those connectors to connectors could be current. This could lamp and horn, and	I loaders, the water proof ctors of work lamp wiring, could cause the water to through the wiring harness. corroded and become unable lead to the malfunction of also the engine could not be

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-V36	[V3-6]	2008 to 2014	1745
EDM-V46	「V4-6」	2008 to 2014	944
EDM-V51	[V5-1]	2008 to 2014	274
EDM-RW05	「LK40Z-5」	2008 to 2014	340
EDM-RX05	[LK50Z-5]	2008 to 2014	396
TOTAL		2008 to 2014	3699