

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 4 1 5	DATE	Aug 8, 2014
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Noise may happen due to a bolt becoming loose because of insufficient fastening force. The bolt fixes the front suspension frame to the body frame. Continuous using the vehicle with the bolt as it is, can detach the bolt and in the worst case, steering function of the vehicle might decrease.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-MA15S	SOLIO	2013	1
		TOTAL	1