

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3 4 1 3	DATE	August 20, 2014
MANUFACTURER	KCM Corporation		
DESCRIPTION OF DEFECT	<p>Engine speed sensor might be broken due to oil ingress from the edge of the sensor which is located in the gear housing.</p> <p>Continuous use of this condition might cause engine stop and disabled machine operation.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-90C5	「90ZV-2」	2012-2013	14
		TOTAL	14