

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3416	DATE	Aug.22 2014
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	It was found that strength of fitting bolts for the caliper of the brake is not strong enough due to improper heat treatment done, therefore, when you keep driving with the condition, you might have some bolts broken and eventually, you might have insufficient brake force.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
UDS - KRC011	KR - 25H	2014	2	
		TOTAL	2	