

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2082	DATE	Aug. 28. 2014
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	the timing-chain tensioners installed in the vehicles affected are not compliant with BMW Motorrad specifications. On account of a manufacturing defect, the timing-chain tensioner is subject to wear. This means that gradually, the timing chain is no longer adequately tensioned and as a result it slips its sprockets, causing the engine to die.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
C600S	BMW C600S	2012-2014	417
C650GT	BMW C650GT	2012-2014	524
		TOTAL	941