

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3427	DATE	August.28. 2014
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	For the inflator of the driver's SRS airbag, a wrong part may have been installed to the diaphragm constituting the airbag inflating gas passage and it can, in the event of the airbag deployment, cause abnormal rise in internal pressure of the inflator by which the container of the inflator could be broken and scattered about, causing injury to the vehicle occupant.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-RM1	CR-V	2011~2012	51
		2012~2013	65
		2013~2014	84
DBA-RM4		2011~2012	31
		2012~2013	30
		2013~2014	52
		TOTAL	313