

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	3 4 2 4	DATE	Aug. 29. 2014
MANUFACTURER	Nichijo Manufacturing Co., Ltd.		
DESCRIPTION OF DEFECT	<p>In the engine of the rotary plow, ① Some for the manufacture of pipes leading to the engine oil filter is inappropriate, cracking has occurred in the piping. Therefore, when being used intact, there is a possibility that the engine oil leaks crack progresses, the engine to failure poor lubrication. ② For the design of the blades of the radiator cooling fan is inappropriate, there is a fan that will resonate. Therefore, if you are using in the state as it is, there is a possibility that the engine reaches the damage a poor cooling fan may be damaged by the resonance.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-R03D	「HTR306」	2012～2014 R03D-0001 ～ R03D-0143	133
TOTAL			133

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where the vehicle that do not qualify are also included.