VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3417	DATE	Aug 28, 2014	
MANUFACTURER	SUZUKI MOTOR CORPORATION			
DESCRIPTION OF DEFECT	Since the fastening force of the bolts that mount the water pump pulley to the water pump is insufficient, there are the bolts loose and abnormal noise occurs. If the vehicle continues to drive, the bolt might be disengaged, water pump belt comes off, warning light will be lit by poor cooling and power failure. In the worst case, there is a possibility that an engine stops and might not be able to restart again.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ZC72S	OMATEM	2013	8,988
DBA-ZD72S	SWIFT		1,357
DBA-MA15S	SOLIO	2013	7,347
DBA-XB32S	SPLASH	2013 ~ 2014	189
DBA-MB15S	DELICA D:2	2013	903
		TOTAL	18,784