

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2093	DATE	Sep. 25. 2014
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Load cycle transients occurring when the vehicle is on the move cause pressure spikes in the engine oil at the radial shaft seal and these high pressures can force the shaft seal out of its seat. Engine oil then escapes into the rear wheel swinging arm and can make its way on to the rear tire. The occurrence of critical riding situations if this happens cannot be precluded.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-R12NA	BMW R1200GS	2013	457
		TOTAL	457