

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2089	DATE	2014/9/24
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	On smart vehicles with 52 kW engines and start/stop function, it is possible that vibrations in the belt drive may occur due to certain operation or usage conditions. The vibrations may lead to premature wear or possibly to a failure of the poly-V-belt. As a result, the alternator as well as the water pump cannot be driven anymore. This is indicated to the customer by the respective indicator lamps in the instrument cluster.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-451380	fortwo coupe	2008	1,046
		2010	1,406
ABA-451380		2012	1,277
		2014	123
CBA-451480		fortwo cabrio	2008
	2010		163
		TOTAL	4,200