

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3436	DATE	Sep 18, 2014
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Welding of the airbag bracket on the passenger seat side possibly splits due to improper welding process. Using the vehicle as it is can put an extraordinary force to the fixing point of the bracket to the vehicle body. In the worst case, the airbag could not have developed normally with breaking of the fixing point at a collision.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-MR31S	HUSTLER	2014	3,473
DBA-MS31S	FLAIR CROSSOVER	2014	273
		TOTAL	3,746