

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|--|------|-------------------|
| CAMPAIGN No. | 3422 | DATE | September 11,2014 |
| MANUFACTURER | MITSUBISHI MOTORS CORPORATION | | |
| DESCRIPTION OF DEFECT | In the brake lamp switch, insulating material may be generated due to invasion of lubricating grease caused by the worker who assembled the switch with using the glove containing lubricating grease. As a result, the brake lamp may not light up due to insufficient conduction caused by the generation of insulating material at the contact point in the switch. For a certain models, it may also cause the phenomenon that the shift lever could not move from the parking position when the brake lamp does not light up. | | |

| T Y P E | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|----------|-----------------|---------------------|-------------------|
| DBA-CW5W | 「OUTLANDER」 | 2007 | 1 |
| | | 2007 | 4 |
| | | 2008～2009 | 5,278 |
| | | 2009 | 1,868 |
| DBA-CW6W | | 2008～2009 | 761 |
| DBA-NA4W | 「GRANDIS」 | 2007～2009 | 71 |
| | | TOTAL | 7,983 |