VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

CAMPAIGN No. 3423 DATE Sep. 2. 2014

MANUFACTURER YAMAHA MOTOR CO., LTD.

DESCRIPTION OF As the headlight electric wiring is arranged inappropriate, some of the electric wires may be bent when the handle is moved to the right and left.

Therefore, if it is used continuously, the electric wires which were bent repeatedly

may be disconnected, and as a result, the headlight may not turned on.

TYPE	COMMERCIAL	MODEL YEAR RECALLED	NUMBER OF	
	NAME		VEHICLE	
EBL-RN34J	MT-09	2 0 1 4		1, 012
	MT-09A			1, 834
			TOTAL	2, 846