## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Import Vehicles

| CAMPAIGN NO.          | 3460 | DATE   | October 30 ,2014 |
|-----------------------|------|--|------------------|
| MANUFACTURER          |      | ISUZU MOTORS LIMITED   |                  |
| DESCRIPTION OF DEFECT |      | In heavy duty trucks, due to the exhaust duct's flexible pipe's structure being not appropriate, there are cases of the bellows of the flexible pipe interfering with the inner pipe while it being vibrated during driving. If the vehicle is used continuously, there could be a possibility of the abrasion getting severer, in the worst case, a hole could be created which could result in a leakage of the exhaust gas. |                  |

| ТҮРЕ   | COMMERCIAL<br>NAME | MODELYEAR<br>RECALLED | NUMBER OF<br>VEHICLE |
|--|--------------------|-----------------------|----------------------|
| LKG-CXE77A<br>OKG-CXE77A                               | [GIGA]             | 2010-2013             | 250                  |
| LKG-CXG77A<br>OKG-CXG77A                               |                    | 2010-2013             | 92                   |
| LKG-CYE77AM<br>OKG-CYE77AM                             |                    | 2010-2013             | 137                  |
| LKG-CYE77AZ<br>OKG-CYE77AZ                             |                    | 2010-2013             | 96                   |
| LKG-CYG77AM<br>OKG-CYG77AM                             |                    | 2010-2013             | 425                  |
| LKG-CYJ77A<br>LKG-CYJ77AA<br>QKG-CYJ77A<br>QKG-CYJ77AA |                    | 2010-2013             | 763                  |
|  |                    | TOTAL                 | 1,763                |