VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	3452	DATE	21 October 2014			
MANUFACTURE	HITACHI CONSTRUCTION MACHINERY CO., LTD					
DESCRIPTION OF DEFECT	Because the greas operation is inappoint listed in the opsupply grease appoint of the parking the pin or the rod by	Because the grease fitting position to the linkage for the parking brake operation is inappropriate. And instruction of grease for parking brake is not listed in the operation and instruction manual. So that it does not supply grease appropriately. So that there is possibility the pin and the rod of the parking brake linkage may adhere. If it will use continuously, the pin or the rod breaks by adherence, and parking brake might not work when it is the worst.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
KDN-HS69	「ZW90」	2009-2014	133	
KDN-S69		2009-2010	28	
		TOTAL	161	