

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3 4 5 1	DATE	October 20, 2014
MANUFACTURER	KCM Corporation		
DESCRIPTION OF DEFECT	When turning the machine, there is a potential that the brake valve hose may be damaged by the steering stopper bracket, resulting in decreased braking power. This is due to an interference of the hose and the bracket, caused by the improper assembly production order.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-80C5	「80ZV-2」	2012-2013	43
JDS-RF06	「LK270Z-6」	2012-2013	2
TOTAL			45