## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

			Domestic Import Vehicles	
CAMPAIGN No.	Gai-2094	DATE	Oct 21, 2014	
MANUFACTURE	Harley–Davidson Motor Company			
	(Japanese Importer : Harley–Davidson Japan K.K. )			
DESCRIPTION OF DEFECT	On some of these motorcycles, the hydraulic clutch system may develop a tear in the primary cup (seal)			
	on the master cylinder piston. If this occurs, the system may lose the ability to maintain sufficient lift to			
	keep the clutch disengaged. If this condition remains undetected, it could allow the motorcycle to			
	"creep" forward from a stop, which could lead to a loss of control of the vehicle possibly causing a			
	crash. Harley–Davidson has initiated this recall to correct this condition in the affected motorcycles.			
	Please keep in mind that this applies to your motorcycle even if you have replaced the original equipment			
	clutch master cylinder with a Harley–Davidson Parts and Accessories master cylinder.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
EBL-FLHM	STREET GLIDE	2014	1,040
EBL-FLHL	ULTRA LIMITED	2014	417
EBL-FLHL	ELECTRA GLIDE ULTRA CLASSIC	2014	237
TEN	CVO™ LIMITED	2014	194
PG8	CVO™ ROAD KING	2014	162
TF9	CVO™ SOFTAIL DELUXE	2014	165
TD9	CVO™ BREAKOUT	2014	344
EBL-TGL	ELECTRA GLIDE ULTRA CLASSIC	2014	375
TC8	CVO™ ROAD GLIDE CUSTOM	2013	2
		TOTAL	2,936