

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3 4 4 9	DATE	O c t . 1 5 . 2 0 1 4
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Because of the length of the electric wire connected to the positive terminal of the battery and the shape of the seat bracket which is inadequate, the electric wire may be positioned over the seat bracket. When that happens, the electric wire may be caught between the seat and the seat bracket. Therefore, if it is used continuously, the coating of the said electric wire may be damaged and as a result, a short-circuit may occur. In the worst case scenario, it may lead to a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
E B L - R M 0 7 J	MT - 0 7	2 0 1 4	7 4 2
	MT - 0 7 A		1 , 0 7 6
		TOTAL	1 , 8 1 8