

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2097	DATE	2014/10/15
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	Impairment in the conductivity can occur at the contact between bulb mount and tail lamp connector. The impairment in the conductivity at the contact can lead to reduced brightness of the lamps and, in the most unfavorable case, to the failure of the tail lamp. In this case, the driver immediately receives a specific warning message in the instrument cluster.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-204046	C180 KOMPRESSOR	2008	1
DBA-204041	C200 KOMPRESSOR	2008	10,865
		2009	5,457
		2010	1,608
DBA-204048	C200 CGI	2010	2,503
		2011	3,939
DBA-204047	C250 CGI	2010	468
		2011	240
DBA-204052	C250	2008	3,355
		2009	1,469
DBA-204054	C300	2008	1,403
		2009	411
		2010	401
		2011	278
CBA-204077	C63	2008	205
		2009	770
		2010	359
		2011	138
DBA-204246	C180 KOMPRESSOR STATIONWAGON	2008	2
DBA-204241	C200 KOMPRESSOR STATIONWAGON	2008	1,041
		2009	2,676
		2010	330

DBA-204241	C200 KOMPRESSOR STATIONWAGON	2011	777
DBA-204248	C200 CGI STATIONWAGON	2010	1,121
		2011	2,474
		2012	1
DBA-204247	C250 CGI STATIONWAGON	2010	244
		2011	194
DBA-204252	C250 STATIONWAGON	2008	429
		2009	763
DBA-204254	C300 STATIONWAGON	2010	51
		2011	119
CBA-204277	C63 STATIONWAGON	2008	31
		2009	154
		2010	65
		2011	75
		TOTAL	44,417