

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3444	DATE	October 9 ,2014
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		Some of mid-duty dump trucks have lights (such as taillight, brake light, reverse light and direction indicator light) of which wiring harnesses are not properly protected. When it snows, the wiring harnesses will have snow on them. If the trucks are kept in operation under such a condition, the snow sticking to their surfaces will turn into ice to stress the wiring harnesses when they are shaken while the trucks are running. If things go wrong, the wiring harnesses may be disconnected, resulting in the problem that the rear lights do not turn on.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-FRR90S1 SKG-FRR90S2 TKG-FRR90S1 TKG-FRR90S2	[FORWARD]	2011-2014	10,795
		TOTAL	10,795