

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 4 4 7	DATE	Oct.2.2014
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Due to the inappropriate jig for inspection in the manufacture of the brake master cylinder, there may be a crack in the flange of the master cylinder. If the vehicle continues to be driven in this condition, the crack can be grown and the portion may break. As a result, braking distance may increase.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-M20	NV200 VANETTE	2014	27
		TOTAL	27