

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3439	DATE	Oct 2, 2014
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	The airbag may make faulty operation due to manufacturing fault of the acceleration sensor IC inside the airbag control unit. Therefore there can be possibilities that the airbag does not deploy at a collision with the warning light on, or reversely that the airbag does deploy without any reason as a mistake while driving the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-DA16T	CARRY	2014	25,070
EBD-DR16T	NT100 CLIPPER	2014	3,161
EBD-DG16T	SCRUM	2014	1,408
EBD-DS16T	MINICAB	2014	2,452
		TOTAL	32,091

Vehicles that have the wrong part due to a repair work after manufacturing of the vehicle

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-DA16T	CARRY	2014	14

The part applied to an unknown vehicle because it was shipped as one of service parts

Part Name	Part No.	Shipment Period of the part	Quantity
Airbag Controller	38910-82M00	2014	7
		TOTAL	7