

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3434	DATE	October 2,2014
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to inappropriate material for the brush for the blower motor, if the blower is used repeatedly for long period of time with the maximum air volume, the brush may worn in the early stage. As a result, the rotational speed of the blower may become slower and if use continues under this condition, the blower could stop and it may be impossible to secure the safe visibility due to the mist generated on the windshield.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GBD-U61V	「MINICAB」	2007～2011	33,767
GBD-U62V		2007～2011	16,700
ABA-U61W	「TOWNBOX」	2007～2011	1,811
ABA-U62W		2007～2011	3,221
CBA-U61W		2007～2011	3,400
CBA-U62W		2007～2011	878
GBD-U71V	「CLIPPER」	2007～2011	37,492
GBD-U72V		2007～2011	12,181
ABA-U71W	「CLIPPER RIO」	2007～2011	2,241
ABA-U72W		2007～2011	2,750
CBA-U71W		2007～2011	5,407
CBA-U72W		2010～2011	173
TOTAL			120,021