

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3475	DATE	Nov. 27, 2014
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>The inflator of the driver's airbag may have been placed under inadequate moisture absorption control after it was filled with gas generating propellant during the inflator manufacturing process. In such an inflator, gas generating propellant may expand and become less dense than usual under the influence of external factors such as outside temperature whilst in use. Such gas generating propellant can, in the event of the airbag deployment, cause abnormal rise in internal pressure of the inflator by which the container of inflator could be broken and scattered about, causing injury to the vehicle occupant.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TA-L250S	Mira	2002-2003	23,098
LE-L250V			892
UE-L250V			
TA-L260S			
LE-L260V			150
		TOTAL	27,571