

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3469	DATE	Nov. 27, 2014
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>Due to the inappropriate manufacturing process in acceleration sensor of airbag control computer, crack occurs in the sensor circuit that outputs airbag deployment signal, and the circuit might be disconnected.</p> <p>Therefore, the sensor might output incorrect signal and the airbag unintendedly deploys while driving.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA600S	TANTO	2014	33,280
DBA-LA610S			7,226
		TOTAL	40,506