

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3462	DATE	Nov 27, 2014
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>One of driver seat brackets which mount the driver seat on the vehicle body may get cracks from repetitive loads due to insufficient strength of the bracket. Therefore continuous using of the vehicle as it is can generate abnormal noises and/ or backlash. In the worst case, the bracket might break and the seat might tilt, ending up to the driver being unable to keep his/ her right driving position/ posture.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-MK21S	PALETTE	2008 ~ 2011	192,048
CBA-MK21S		2008 ~ 2011	59,408
DBA-ML21S	ROOX	2009 ~ 2011	86,425
CBA-ML21S		2009 ~ 2011	6,972
		TOTAL	344,853