

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-2118	DATE	November 25, 2014
MANUFACTURER	KTM MOTORRAD AG  (Japanese Importer : KTM Japan KK)		
DESCRIPTION OF DEFECT	Because of improper tightening of lock nut connecting top cap and piston rod, the piston rod detaches from the screw cap, As a result of this, parts inside front fork will be damaged and seized, then front fork itself gets blocked completely in worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
125EXC	「125EXC 6DAYS」	2015	2 UNITS
250EXC	「250EXC 6DAYS」	2015	15 UNITS
250EXC-F	「250EXC-F 6DAYS」	2015	18 UNITS
350EXCEXA42	「350EXC-F 6DAYS」	2015	9 UNITS
500EXCEXA44	「500EXC 6DAYS」	2015	10 UNITS
TE125	「TE125」	2015	2 UNITS
TE250	「TE250」	2015	3 UNITS
FE250	「FE250」	2015	3 UNITS
FE501UAB44	「FE501」	2015	1 UNITS
		TOTAL	63 UNITS