

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3473	DATE	November 20. 2014
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Because of a fault in the internal circuit of the microcomputer controlling the multi-information display readout, the multi-information display may remain blank even when the ignition switch is turned on whereby the distance travelled in such a condition could not be registered on the odometer.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-SC68	GOLDWING	2014	171
	GOLDWING F6B	2014	3
		TOTAL	174