

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3471	DATE	November.13. 2014
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>The inflator of the driver's SRS airbag may have been placed under inadequate moisture absorption control after it was filled with gas generating propellant during the inflator manufacturing process. In such an inflator, gas generating propellant may expand and become less dense than usual under the influence of external factors such as outside temperature whilst in use. Such gas generating propellant can, in the event of the airbag deployment, cause abnormal rise in internal pressure of the inflator by which the container of inflator could be broken and scattered about, causing injury to the vehicle occupant.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-JD1	「THAT'S」	2002～2003	32,782
		2002～2004	7,830
		2002～2003	9
LA-JD2		2002～2003	5,479
		2002～2003	2,089
		2003	1
		TOTAL	48,190