

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2114	DATE	November.13. 2014
MANUFACTURER	HONDA AUTOMOBILE (THAILAND) CO., LTD.		
DESCRIPTION OF DEFECT	<p>The inflator of the driver's SRS airbag may have been placed under inadequate moisture absorption control after it was filled with gas generating propellant during the inflator manufacturing process. In such an inflator, gas generating propellant may expand and become less dense than usual under the influence of external factors such as outside temperature whilst in use. Such gas generating propellant can, in the event of the airbag deployment, cause abnormal rise in internal pressure of the inflator by which the container of inflator could be broken and scattered about, causing injury to the vehicle occupant.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-GD6	「FIT ARIA」	2003～2004	5,520
LA-GD7		2003～2004	900
LA-GD8		2002～2004	10,770
LA-GD9		2003～2004	1,110
DBA-GD6		2004～2005	1,381
		2005	3
DBA-GD7		2004～2005	272
DBA-GD8		2004	2,090
		2005	5
		2006	5
DBA-GD9		2004～2005	545
		2005	2
		2006	1
		2007	1
	2007～2008	2	
		TOTAL	22,607