VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3465	DATE	Nov.12.2014	
MANUFACTURER	TOYOTA			
DESCRIPTION OF DEFECT	In the ball joint which connects the lower arm to the knuckle arm, due to improper maintenance of the conveyance equipment, the rubber boot of the ball joint could come to direct contacts with the conveyance equipment which result in damage to the rubber boot. In this condition, lubricant grease inside the ball joint could leak from the damaged rubber boot causing the ball joint to wear prematurely. In the worst case, the lower ball joint may separate			
	from the knuckle and could cause the vehicle to become inoperative.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ACV40	[CAMRY]	2011	115
DBA-ACV45			16
DAA-AVV50		2011-2014	40,926
DAA-AVV50N	[ALTIS]	2012-2014	389
		TOTAL	41,446