VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3459	DATE	November 7.2014		
MANUFACTURER	YANMAR CO.,LTD.				
DESCRIPTION OF DEFECT	In the transmission of agricultural tractors with rear crawlers there is a possibility that the reverser shaft is cracked during t heavy towing operation because of the insufficient strength of t shaft. If the customer keeps operating the unit, the crack go deeper and deeper. In the worst case, the shaft is broken and t unit becomes unable to be driven.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE	
	「EG437」	2011~2013	237		
_	「EG445」	2011~2013	267		
	「EG453」	2011~2013	426		
			тс	DTAL	930