

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2123	DATE	December 2 nd , 2014
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	One of the intake camshaft components might be faulty. This may lead to insufficient oil supply to the vacuum pump, which creates vacuum to be supplied to the brake booster. As a result, vacuum pump may become stuck because of insufficient lubrication, and vacuum may not be supplied to the brake booster. In the worst case, braking distance may be longer.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-3B20	BMW 320i	2012 - 2013	303
	BMW 320i Touring	2013	34
DBA-3X20	BMW 320i Gran Turismo	2013	1
DBA-3A20	BMW 328i	2011 - 2013	26
	BMW 328i Touring	2012 - 2013	30
DBA-3X28	BMW 328i Gran Turismo	2013	1
DBA-3N28	BMW 428i	2013	3
DBA-XG20	BMW 523i	2011 - 2013	62
DBA-XL20	BMW 523i Touring	2011 - 2013	10
DBA-XG28	BMW 528i	2011 - 2013	24
DBA-XL28	BMW 528i Touring	2011 - 2013	3
DBA-VL20	BMW X1 sDrive 20i	2012 - 2013	76
DBA-VM20	BMW X1 xDrive 20i	2011 - 2013	125
	BMW X1 xDrive 28i	2011 - 2013	14
DBA-WX20	BMW X3 xDrive 20i	2012 - 2013	36
	BMW X3 xDrive 28i	2012 - 2013	5
DBA-LL20	BMW Z4 sDrive 20i	2011 - 2013	32
		TOTAL	785