

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3477	DATE	Dec. 2 2014
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty buses, the strength of the heater hose is insufficient. The reinforcement fabric in the hose may break due to the water pressure. If the bus continues to be used in this condition, the heater hose may break by the water pressure, leading to the leakage of coolant. This will lower the performance of the defroster and it will not be able to maintain the clear view of the lower part of the windshield.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-MS96VP	「FUSO AERO ACE」	2010~2012	469
	「FUSO AERO QUEEN」	2010~2012	92
QRG-MS96VP	「FUSO AERO ACE」	2012~2014	834
	「FUSO AERO QUEEN」	2012~2014	128
LKG-AS96VP	「SPACEARROW A」	2010~2011	12
	「SPACEWING A」	2010~2011	5
		TOTAL	1,540